



中石化南京催化剂有限公司十一月生产废水监测数据（自测）

监测日期	采样地点及监测点 编号名称	监测项目																	
		PH			总磷 (mg/L)			氨氮 (mg/L)			悬浮物 (mg/L)			TDS (mg/L)			COD (mg/L)		
		污染物浓度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓度 (mg/L)	排放上限 (mg/L)	是否达标
2021.11.1	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.5	6-9	是	1.3	≤5	是	6.5	≤45	是	106	≤400	是	853	≤10000	是	38	≤500	是
2021.11.2	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.2	6-9	是	未检出	≤5	是	7.9	≤45	是	108	≤400	是	440	≤10000	是	51	≤500	是
2021.11.3	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.1	6-9	是	3.6	≤5	是	10.1	≤45	是	76	≤400	是	192	≤10000	是	89	≤500	是
2021.11.4	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.4	6-9	是	未检出	≤5	是	3	≤45	是	94	≤400	是	429	≤10000	是	167	≤500	是
2021.11.5	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.4	6-9	是	1	≤5	是	3	≤45	是	56	≤400	是	621	≤10000	是	未检出	≤500	是
2021.11.6	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.4	6-9	是	0.8	≤5	是	5.8	≤45	是	82	≤400	是	697	≤10000	是	44	≤500	是
2021.11.7	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.3	6-9	是	0.7	≤5	是	3.4	≤45	是	49	≤400	是	880	≤10000	是	73	≤500	是
2021.11.8	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.3	6-9	是	未检出	≤5	是	3.2	≤45	是	82	≤400	是	771	≤10000	是	35	≤500	是
2021.11.9	进水口	10.5			241.5														
	WS-01-2016	7.2	6-9	是	未检出	≤5	是	4.3	≤45	是	96	≤400	是	1018	≤10000	是	43	≤500	是
2021.11.10	进水口	10.7			326.7														
	WS-01-2016	7.4	6-9	是	0.7	≤5	是	3.9	≤45	是	156	≤400	是	4376	≤10000	是	229	≤500	是
2021.11.11	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.5	6-9	是	2.8	≤5	是	16.6	≤45	是	124	≤400	是	6921	≤10000	是	314	≤500	是
2021.11.12	进水口	10.6			180.4														
	WS-01-2016	7.7	6-9	是	2.9	≤5	是	17.5	≤45	是	82	≤400	是	9970	≤10000	是	470	≤500	是
2021.11.13	进水口	10.6			34.1														
	WS-01-2016	7.5	6-9	是	4.8	≤5	是	24.2	≤45	是	146	≤400	是	4376	≤10000	是	184	≤500	是
2021.11.14	进水口	10.5			292.7														
	WS-01-2016	7.6	6-9	是	2	≤5	是	17.9	≤45	是	101	≤400	是	9211	≤10000	是	248	≤500	是
2021.11.15	进水口	10			254.5														
	WS-01-2016	7.3	6-9	是	1.4	≤5	是	10.1	≤45	是	110	≤400	是	1889	≤10000	是	99	≤500	是
2021.11.16	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.6	6-9	是	2.4	≤5	是	8.7	≤45	是	99	≤400	是	9566	≤10000	是	135	≤500	是
2021.11.17	进水口	10.2			75.7														
	WS-01-2016	7.1	6-9	是	3.6	≤5	是	14.7	≤45	是	111	≤400	是	3499	≤10000	是	145	≤500	是
2021.11.18	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.4	6-9	是	1.5	≤5	是	6	≤45	是	119	≤400	是	2698	≤10000	是	92	≤500	是
2021.11.19	进水口	11.2			325.5														
	WS-01-2016	7.4	6-9	是	0.4	≤5	是	2.9	≤45	是	100	≤400	是	4911	≤10000	是	205	≤500	是
2021.11.20	进水口	/	/		/	/		/	/		/	/		/	/		/	/	
	WS-01-2016	7.6	6-9	是	3.6	≤5	是	15.6	≤45	是	102	≤400	是	7477	≤10000	是	192	≤500	是



扫描全能王 创建



2021.11.21	进水口	10			77.9											1962		
	WS-01-2016	7.4	6-9	是	0.4	≡5	是	7.5	≡45	是	82	≡400	是	4355	≡10000	是	181	≡500
2021.11.22	进水口	10.4			75.5											871		
	WS-01-2016	6.8	6-9	是	未检出	≡5	是	7	≡45	是	104	≡400	是	5366	≡10000	是	148	≡500
2021.11.23	进水口	10.5			108.9											857		
	WS-01-2016	7	6-9	是	未检出	≡5	是	9.5	≡45	是	99	≡400	是	1734	≡10000	是	50	≡500
2021.11.24	进水口	/			/											/		
	WS-01-2016	7.8	6-9	是	未检出	≡5	是	6.7	≡45	是	104	≡400	是	4966	≡10000	是	190	≡500
2021.11.25	进水口	10.1			74.9											501		
	WS-01-2016	7.6	6-9	是	2.1	≡5	是	10.5	≡45	是	77	≡400	是	5485	≡10000	是	288	≡500
2021.11.26	进水口	/			/											/		
	WS-01-2016	7.5	6-9	是	1.2	≡5	是	13	≡45	是	99	≡400	是	2663	≡10000	是	138	≡500
2021.11.27	进水口	10.5			137.3											1125		
	WS-01-2016	7.6	6-9	是	2.3	≡5	是	10.7	≡45	是	84	≡400	是	3147	≡10000	是	183	≡500
2021.11.28	进水口	/			/											/		
	WS-01-2016	7.8	6-9	是	2.4	≡5	是	9.1	≡45	是	87	≡400	是	4013	≡10000	是	201	≡500
2021.11.29	进水口	10			90.9											884		
	WS-01-2016	6.8	6-9	是	0.8	≡5	是	14	≡45	是	99	≡400	是	2663	≡10000	是	284	≡500
2021.11.30	进水口	/			/											/		
	WS-01-2016	7.4	6-9	是	0.6	≡5	是	5.7	≡45	是	103	≡400	是	2281	≡10000	是	187	≡500

注：/表示无外排，WS-01-2016为污水接管口。



扫描全能王 创建