



中石化南京催化剂有限公司六月生产废水监测数据（自测）

监测日期	采样地点及监测点 编号名称	监测项目																	
		PH			总磷 (mg/L)			氨氮 (mg/L)			悬浮物 (mg/L)			TDS (mg/L)			COD (mg/L)		
		排放上限	是否达标		污染物浓 度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓 度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓 度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓 度 (mg/L)	排放上限 (mg/L)	是否达标	污染物浓 度 (mg/L)	排放上限 (mg/L)	是否达标
2023.6.1	进水口	10.2			319.5												/		
	WS-01-2016	7.4	6-9	是	1.3	≤5	是	6.1	≤45	是	82	≤400	是	5942	≤10000	是	197	≤500	是
	WS-01-2016	/	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是
2023.6.2	进水口	2.9			3246.8												/		
	WS-01-2016	7.6	6-9	是	3	≤5	是	11.3	≤45	是	84	≤400	是	3727	≤10000	是	376	≤500	是
	WS-01-2016	/	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是
2023.6.3	进水口	2.9			3091.4												/		
	WS-01-2016	7.4	6-9	是	1.2	≤5	是	11.3	≤45	是	94	≤400	是	2819	≤10000	是	241	≤500	是
	WS-01-2016	7.4	6-9	是	0.7	≤5	是	12.7	≤45	是	95	≤400	是	3864	≤10000	是	293	≤500	是
2023.6.4	进水口	2.9			3085.5												/		
	WS-01-2016	7.3	6-9	是	1.3	≤5	是	3.6	≤45	是	61	≤400	是	1325	≤10000	是	107	≤500	是
	WS-01-2016	/	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是
2023.6.5	进水口	3.1			3090.9												/		
	WS-01-2016	7	6-9	是	2.4	≤5	是	3.5	≤45	是	82	≤400	是	889	≤10000	是	108	≤500	是
	WS-01-2016	8.1	6-9	是	1.3	≤5	是	2.4	≤45	是	94	≤400	是	236	≤10000	是	58	≤500	是
2023.6.6	进水口	/			/												/		
	WS-01-2016	7.2	6-9	是	1.2	≤5	是	7.6	≤45	是	89	≤400	是	1421	≤10000	是	137	≤500	是
	WS-01-2016	7.6	6-9	是	1.3	≤5	是	3.8	≤45	是	62	≤400	是	136	≤10000	是	<20	≤500	是
2023.6.7	进水口	/			/												/		
	WS-01-2016	7.2	6-9	是	1.3	≤5	是	7.3	≤45	是	75	≤400	是	2267	≤10000	是	187	≤500	是
	WS-01-2016	8.2	6-9	是	未检出	≤5	是	2.6	≤45	是	12	≤400	是	328	≤10000	是	21	≤500	是
2023.6.8	进水口	5.8			410.5												/		
	WS-01-2016	7.3	6-9	是	1.5	≤5	是	4.5	≤45	是	82	≤400	是	1397	≤10000	是	214	≤500	是
	WS-01-2016	7.1	6-9	是	1.2	≤5	是	5.1	≤45	是	84	≤400	是	2208	≤10000	是	219	≤500	是
2023.6.9	进水口	9			151.8												/		
	WS-01-2016	6.9	6-9	是	0.4	≤5	是	3.7	≤45	是	52	≤400	是	2913	≤10000	是	394	≤500	是
	WS-01-2016	/	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是
2023.6.10	进水口	/			/												/		
	WS-01-2016	6.9	6-9	是	0.9	≤5	是	3.6	≤45	是	46	≤400	是	4496	≤10000	是	433	≤500	是
	WS-01-2016	/	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是
2023.6.11	进水口	9.1			339.6												/		
	WS-01-2016	7	6-9	是	1.8	≤5	是	6.3	≤45	是	47	≤400	是	4890	≤10000	是	340	≤500	是
	WS-01-2016	7	6-9	是	2.3	≤5	是	5.1	≤45	是	154	≤400	是	6167	≤10000	是	341	≤500	是
2023.6.12	进水口	8.8			361.4												/		
	WS-01-2016	7.1	6-9	是	1.6	≤5	是	9.6	≤45	是	120	≤400	是	5932	≤10000	是	306	≤500	是
	WS-01-2016	7	6-9	是	1.9	≤5	是	6.9	≤45	是	137	≤400	是	6886	≤10000	是	445	≤500	是
2023.6.13	进水口	/			/												/		
	WS-01-2016	7	6-9	是	1.4	≤5	是	6.1	≤45	是	49	≤400	是	5655	≤10000	是	310	≤500	是
	WS-01-2016	/	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是



2023.6.14	WS-01-2016	8.1	6-9	是	2.1	≤5	是	11.2	≤45	是	30	≤400	是	4203	≤10000	是	325	≤500	是
	WS-01-2016	8.3	6-9	是	1	≤5	是	11	≤45	是	40	≤400	是	4770	≤10000	是	367	≤500	是
	WS-01-2016	8.3	6-9	是	237.5												/		
2023.6.15	WS-01-2016	7.6	6-9	是	2.5	≤5	是	22.8	≤45	是	44	≤400	是	3670	≤10000	是	434	≤500	是
	WS-01-2016	7.6	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是
	WS-01-2016	7.6	6-9	是	199.5												/		
2023.6.16	WS-01-2016	7.1	6-9	是	2.8	≤5	是	8.8	≤45	是	41	≤400	是	4369	≤10000	是	192	≤500	是
	WS-01-2016	/	6-9	是	/	≤5	是	/	≤45	是	/	≤400	是	/	≤10000	是	/	≤500	是
	WS-01-2016	/	6-9	是	/												/		
2023.6.17	WS-01-2016	6.9	6-9	是	1.1	≤5	是	13.5	≤45	是	48	≤400	是	4335	≤10000	是	437	≤500	是
	WS-01-2016	7.3	6-9	是	0.6	≤5	是	13.9	≤45	是	80	≤400	是	4201	≤10000	是	299	≤500	是
	WS-01-2016	9.6	6-9	是	771.3												/		
2023.6.18	WS-01-2016	6.9	6-9	是	0.9	≤5	是	5.4	≤45	是	83	≤400	是	3776	≤10000	是	419	≤500	是
	WS-01-2016	8.3	6-9	是	0.3	≤5	是	1	≤45	是	33	≤400	是	335	≤10000	是	41	≤500	是
	WS-01-2016	9.6	6-9	是	230.6												/		
2023.6.19	WS-01-2016	6.9	6-9	是	1	≤5	是	8.2	≤45	是	112	≤400	是	3285	≤10000	是	383	≤500	是
	WS-01-2016	8	6-9	是	2	≤5	是	2.1	≤45	是	41	≤400	是	248	≤10000	是	<20	≤500	是
	WS-01-2016	9.6	6-9	是	230.9												/		
2023.6.20	WS-01-2016	8	6-9	是	1.7	≤5	是	4.7	≤45	是	38	≤400	是	57	≤10000	是	<20	≤500	是
	WS-01-2016	7.9	6-9	是	0.5	≤5	是	2.1	≤45	是	33	≤400	是	147	≤10000	是	142	≤500	是
	WS-01-2016	6.7	6-9	是	168.1												/		
2023.6.21	WS-01-2016	7.9	6-9	是	未检出	≤5	是	0.9	≤45	是	32	≤400	是	152	≤10000	是	<20	≤500	是
	WS-01-2016	7.1	6-9	是	1.3	≤5	是	6.4	≤45	是	46	≤400	是	2337	≤10000	是	203	≤500	是
	WS-01-2016	/	6-9	是	/												/		
2023.6.22	WS-01-2016	7.9	6-9	是	0.5	≤5	是	1.8	≤45	是	34	≤400	是	119	≤10000	是	62	≤500	是
	WS-01-2016	7.1	6-9	是	1.4	≤5	是	1.4	≤45	是	80	≤400	是	2530	≤10000	是	305	≤500	是
	WS-01-2016	7.6	6-9	是	222.6												/		
2023.6.23	WS-01-2016	6.8	6-9	是	1.5	≤5	是	9.5	≤45	是	91	≤400	是	3779	≤10000	是	220	≤500	是
	WS-01-2016	7.6	6-9	是	未检出	≤5	是	2.8	≤45	是	44	≤400	是	173	≤10000	是	26	≤500	是
	WS-01-2016	/	6-9	是	/												/		
2023.6.24	WS-01-2016	6.7	6-9	是	1.9	≤5	是	4	≤45	是	61	≤400	是	3465	≤10000	是	206	≤500	是
	WS-01-2016	7	6-9	是	0.8	≤5	是	2	≤45	是	83	≤400	是	3095	≤10000	是	242	≤500	是
	WS-01-2016	7.7	6-9	是	134.1												/		
2023.6.25	WS-01-2016	7.1	6-9	是	未检出	≤5	是	3.2	≤45	是	45	≤400	是	846	≤10000	是	83	≤500	是
	WS-01-2016	7	6-9	是	1.5	≤5	是	5.8	≤45	是	83	≤400	是	4309	≤10000	是	252	≤500	是
	WS-01-2016	7.7	6-9	是	169.4												/		
2023.6.26	WS-01-2016	7.1	6-9	是	1.3	≤5	是	2.8	≤45	是	67	≤400	是	4568	≤10000	是	261	≤500	是
	WS-01-2016	7	6-9	是	0.7	≤5	是	4.2	≤45	是	68	≤400	是	3882	≤10000	是	243	≤500	是
	WS-01-2016	7.3	6-9	是	89.6												/		
2023.6.27	WS-01-2016	6.9	6-9	是	1.2	≤5	是	7.4	≤45	是	83	≤400	是	3494	≤10000	是	325	≤500	是
	WS-01-2016	7.6	6-9	是	0.7	≤5	是	<0.4	≤45	是	43	≤400	是	310	≤10000	是	44	≤500	是
	WS-01-2016	9	6-9	是	244.6												/		
2023.6.28	WS-01-2016	7.7	6-9	是	0.4	≤5	是	<0.4	≤45	是	31	≤400	是	288	≤10000	是	<20	≤500	是
	WS-01-2016	7.1	6-9	是	1.5	≤5	是	6.6	≤45	是	54	≤400	是	2353	≤10000	是	252	≤500	是
	WS-01-2016	/	6-9	是	/												/		



2023.6.29	WS-01-2016	7.7	6-9	是	未检出	≤5	是	1	≤45	是	68	≤400	是	140	≤10000	是	35	≤500	是
	WS-01-2016	7.4	6-9	是	未检出	≤5	是	<0.4	≤45	是	36	≤400	是	136	≤10000	是	<20	≤500	是
2023.6.30	进水口	8.8			307											/			
	WS-01-2016	7	6-9	是	2.1	≤5	是	15.2	≤45	是	84	≤400	是	1983	≤10000	是	284	≤500	是
	WS-01-2016	7.6	6-9	是	1	≤5	是	1.3	≤45	是	65	≤400	是	102	≤10000	是	<20	≤500	是

注：/表示无外排，WS-01-2016为污水接管口。

